

Author name: P. Lowe

Date of submission: Wednesday, 3 October 2018

Submission: the meter on my house was replaced (without consultation) and the MEN link was not replaced. It was previously contained in the plug-in style meter. The meter board box also received damage and the 3g aerial was crooked. The later comment is just an observation but adds to the notion that the entire job was poorly and unprofessionally undertaken.